

	Type	L #	Hits	Search Text	DBs
1	BRS	L1	11	(vcsel (vetrical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (ative gain)	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
2	BRS	L2	91	(vcsel (vetrical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (active gain)	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
3	BRS	L3	58	(vcsel (vetrical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (active gain) same (reflector dbr)	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
4	BRS	L4	0	(vcsel (vetrical near3 resonator)) same (etch\$3 near3 runout) same (active gain) same (reflector dbr)	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B

	Time Stamp	Comments	Error Definition	Errors
1	2005/11/15 14:33			
2	2005/11/15 13:14			
3	2005/11/15 14:35			
4	2005/11/15 14:27			

	Type	L #	Hits	Search Text	DBs
5	BRS	L5	1	((vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (active gain) same (reflector dbr)	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
6	BRS	L6	5	(vcSEL (vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (active gain) same (reflector dbr) same (current near3 aperture)	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
7	BRS	L7	0	372/43.ccls. and (vcSEL (vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (active gain)	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
8	BRS	L8	0	372/45.ccls. and (vcSEL (vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (active gain)	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B

	Time Stamp	Comments	Error Definition	Errors
5	2005/11/15 14:27			
6	2005/11/15 14:28			
7	2005/11/15 14:34			
8	2005/11/15 14:34			

	Type	L #	Hits	Search Text	DBs
9	BRS	L9	0	372/43.ccls. and ((vcSEL (vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (ative gain))	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
10	BRS	L10	0	372/43.ccls. and(vcSEL (vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (active gain) same (reflector dbr)	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
11	BRS	L11	0	372/43.ccls. and (vcSEL (vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (active gain) same (reflector dbr)	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
12	BRS	L12	0	372/43.ccls. and ((vcSEL (vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (active gain) same (reflector dbr))	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B

	Time Stamp	Comments	Error Definition	Errors
9	2005/11/15 14:34			
10	2005/11/15 14:35			
11	2005/11/15 14:36			
12	2005/11/15 14:36			

	Type	L #	Hits	Search Text	DBs
13	BRS	L13	4571	372/43.ccls.	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
14	BRS	L14	0	372/45.ccls. and ((vcSEL (vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (active gain) same (reflector dbr))	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
15	BRS	L15	0	372/44.ccls. and ((vcSEL (vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (active gain) same (reflector dbr))	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
16	BRS	L16	0	372/46.ccls. and ((vcSEL (vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 adj stop\$3)) same (active gain) same (reflector dbr))	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B

	Time Stamp	Comments	Error Definition	Errors
13	2005/11/15 14:36			
14	2005/11/15 14:37			
15	2005/11/15 14:37			
16	2005/11/15 14:38			

	Type	L #	Hits	Search Text	DBs
17	BRS	L17	0	372/46.ccls. and ((vcse1 (vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 near stop\$3)) same (active gain) same (reflector dbr))	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
18	BRS	L18	0	372/45.ccls. and ((vcse1 (vertical near3 resonator)) same (anti\$oxid\$5 non\$oxid\$5 (etch\$3 near stop\$3)) same (active gain) same (reflector dbr))	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B

	Time Stamp	Comments	Error Definition	Errors
17	2005/11/15 14:38			
18	2005/11/15 14:38			